(19)日本国特許庁(JP)

(12) 公開特許公報(A)

(11)特許出願公開番号 特開2002-157172 (P2002-157172A)

(43)公開日 平成14年5月31日(2002.5.31)

(51) Int.Cl.7	裁別記号	FΙ	∱-73-}*(参考)
G06F 13/00	351	C06F 13/00	351N 5B089
			0.11.70

審査請求 未請求 請求項の数4 OL (全 13 頁)

(21)出願番号	特職2000-357624(P2000-357624)	(71)出職人 000005108		
		株式会社日立製作所		
(22) 出版日	平成12年11月20日 (2000.11.20)	東京都千代田区神田豊河台四丁目 6 番地		
		(72)発明者 木原 健一		
		神奈川県川崎市麻生区王禅寺1099番地 株		
		式会社日立製作所システム開発研究所内		
		(72)発明者 平田 使明		
		神奈川県川崎市麻生区王都寺1099番地 株		
		式会社日立製作所システム開発研究所内		
		(74)代理人 100075096		
		弁理士 作田 議夫		
		Fターム(参考) 58089 CA11 JA35 JB16 KA10 KA13		
		KC47 WA07		
		RO41 MAO1		


(54) 【発明の名称】 計測情報プローカー

(57)【要約】

【課題】ネットワークやコンピュータの稼動状況や負荷の状況を把握するため、各種リソースに対する計測が行われるが、計測機能(計測機器)に対する L/F (インターフェイス)には、SNMPやCIM、ARMなど様々な仕機があり、管理アプリケーションが計測機能にアクセスするためには各1/F仕様に対応するプログラムを作成する必要があった。

【解決手段】本発明では計測情報を収集/提供するための専用装置(計測情報プローカー)を用いる。この計測 情報プローカーは、統一されたI/F仕様に基づ計測 要求を各種1/F仕様へ変換する機能、計測結果の収集機 能、計測結果の出力(配送)機能を持つ。計測情報の収集機 が、計測結果の出力(配送)機能を持つ。計測情報プローカーを用いることにより、管理ププリケーションは一つのI/Fを実装するだけで各種計測結果と修る。

図 3 計測情報プローカーの様成と他との関係



【特許請求の範囲】

【請求項1】 コンピュータ機器やネットワーク機器などで構成されるコンピュータシステムにおいて、

前記コンピュータ機器やネットワーク機器などのハード ウェアやファームウェア、ソフトウェアなどのリソース の状態を計測あるいはチェックし、前記計測あるいはチェックした結果を他に伝達する機能を有する計測機能 と、

計測項目を特定する情報から、前記計測機能に対する計 測あるいはチェックの指示手段の種類、または前記計測 機能からの計測あるいはチェック結果の収集手段の種類 を導き出し、

前記計測機能に対する計測あるいはチェックの指示、または前記計測機能が提供する計測あるいはチェック結果 の収集を行う計測情報プローカーと、を有することを特 徴とするコンピュータシステム。

【請求項2】 コンピュータ機器やネットワーク機器などで構成されるコンピュータシステムにおいて、 前記コンピュータ機器やネットワーク機器などのハード ウェアやファームウェア、ソフトウェアなどのリソース の状態を評拠あるいはチェックし、前記記測あるいはチェックした結果を他に伝達する機能を有する計測機能

計測対象を特定する情報と、計測項目を特定する情報 と、から、前記計測機能を特定する情報と、助記計測機 能に対する計測指示手段の種類とたは前記計測機能から の計測結果収集手段の種類と、を導き出し、

前記計測機能に対する計測あるいはチェックの指示、ま たは前記計測機能が提供する計測あるいはチェック結果 の表します。 を行う計測情報プローカーと、を有することを 特徴とするコンピュータンステム。

「請求項3】 請求項1または請求項2記載のコンピュータシステムであって、

前記計測構能プローカーは、実施予定の、あるいは現在 実施中の、前記計測機能に対する計測あるいはオナット の指示の発行処理、または前記計測機能が提供する計測 あるいはチェック結果の収集処理、を実行する際に必要 な情報を、複数関係する手段を有することを特徴とす るコンビューダシステム。

【請求項4】 請求項1または請求項2記載のコンピュ ータシステムであって、

前記計測情報プローカーは前記計測機能から収集した計 測あるいはチェック結果を、複数の計測結果出力先に出 力することが可能なことを特徴とするコンピュータシス テム。

【発明の詳細な説明】

[0001]

٤.

【発明の属する技術分野】本発明はコンピュータシステム、特にネットワークによって複数のコンピュータが接続され 使用される分散コンピューティング環境での

ネットワーク/システム上に存在する各種リソースの稼 動や性能に関する情報収集に関する。

[0002]

【従来の技術】コンピュータシステムを運用・保守して いくためには、システムを構成する要素機能の動作を監 視することが必要である。正常に移動しているか、過負 荷になっていないかを常時監視することで、システム異 常の早期発見や将来必要となる性能・容量の予測などが 可能になる。

【0003】監視機能を実現するための中心機能は、情 解収集機能および計測機能である。監視対象の複動状況 チェック結果や負荷の計測結果などを取得した上で、正 常/異常の平断を行い、異常あるいは異常につながる兆 機が見受けられれば、必要な対策を取る。

【0004】ネットワーク/システム内の構成機器から 情報を収集する手段は、個々の機器自身が持っている場 合もあるし、計測専用の機器やツールなどもある。しか し、それらの情報収集機能に対するアクセス手段は一様 ではなく、機器の雑類によって異なる。

【0005】たとえばネットワーク機器の場合、ネットワーク管理用の標準プロトコルとしてIETF(Interest Engineering Task Force)で規定されているSNMP(Simple Network Management Protocol)があるが、コンピュータ管理用のインターフェイスとしてはDMTF(Desktop Management Task Force)で規定されているWBEM(Web-based Enterprise Management)がある。

【0006】さらに同じ種類の機器でも、アクセス手段 が一つとは限らない。たとえばネットワーク機器の場 合、前述のSNMPの他に、ネットワーク機器へンダ固 有のアクセス手段を持っていることが多い。そして、よ り高度な機能を引き出せるのは後者であるのが一般的で ある。

【0007】また、ソフトウェアにはソフトウェア専用 の監視機能、情器収集機能しある。たとはゴコンビュー タ上で動作するアプリケーションソフトに関する報動・ 性距監視については、The Open Groupで 策定された標準仕様であるARM (Application Respon se Management) と呼ばれるインターフェイスがある。 【0008】

(発明が解決しようとする課題) 従来技術で述べた通り、コンピュータシステム内の要素機能の積勢や性能に 助する情報収集機能に対するアクセス手段の種類は数多い。従来、これらの情報収集機能にアクセスするために は、情報収集機能を利用する側(管理アプリケーション 側)が圏別のアクセス手段に対応したロジックを用意す る必要があり、アプリケーションの開発負担およびシス テムに対する実装上の負担が大きかった。

【0009】本発明は、これらの負担を軽減することを 目的とする。 【0010】なお、本発明は各種監視機能実現のための 計測処理や情報収集処理に関するものである。本文では 以下「計測」という表現を用いるが、各種監視・管理に 必要な情報収集の意味である。

[0011]

【課題を解決するための手段】前記課題を解決するため に、本発明では、計測機能への情報収集処理を代行する 計測情報プローカーを利用することで、計測機能に対す る箇有の1/Fを認載する。

【0012】計測情報プローカーの構成要素は以下の構 成要素を持ち、計測情報を必要とするアプリケーション (管理アプリケーション) に単一のアクセス窓口を提供 する。

【0013】(1)計測要求受付機能

アプリケーションから発行される計測情報の要求を受け 取る機能。

【0014】(2)計測手段選択機能

前記要求の内容に応じて、計測機能へのアクセス手段を 選択する機能。

【0015】(3)計測指示機能

計測機能に対応したアクセス方法で、計測機能に計測指示を発行する機能。

【0016】(4)計測結果収集機能

計測機能から計測結果を収集する機能。

[0017]

【発明の実施の形態】1. 全体のシステム構成 本発明のシステム全体の構成要素は図1に示す通り、計 測様作部2と計測情報プローカー110、計測機能131、計 測対象132、出力先14であり、それらはネットワーク22 によって結ばれている。

【0018】なお図1ではを構成要素がネットワーク2 によって隔てられた別の機器210上に存在する形で描い ているが、同一機器210上に複数の構成要素が実装され ても良い。たとえば、計測操作部12を計測情報プローカ ー110が同一機器210上に実装されても良い。また、計測 対象13324必ずしもネットワーク22に接続されている必 要はなく、計測機能131から計測可能な状態であれば良い。

【0019】1.1 各部の機能概要

計測接件部2以上計測情報プローカー110に対して、計測 情報プローカー110の各種動作に関する指示を発行する 機能を有する。なお計測接件部2以計測情報プローカー 管理絡17の機能にアクセス可能な搬末(コンソール) やアアリケーション (ローカル/リモートアプリケーション)を想定している。

【0020】計測情報ブローカー116は本発明の主体であり、計測操作部12からの指示に基づいて計測部331に対する計測指示や計測結果の出力先14への送信を行う機能を有する。計測情報ブローカー110の詳細については「2.計測情報プローカーの詳細」で述べる。

【0021】計瀬機能131は計測情報ブローカー110から の指示に基づき計測対象132を計測し、計測結果を計測 情報ブローカー110に該す機能を持つ。なお計測機能131 自体が計測機能を持つ必要はなく、さらに別の計測機能 への中継機能であっても良い。

【0022】計測対象132は計測の対象であり、計測部1 31によって計測される。計測対象132は、ネットワーク やルータ装置、コンピュータ装置などのハードウェア装 面の他、機器上で稼動するファームウェアまたはソフト ウェアであっても良い。

【0023】出力先14は計測結果の出力先である。ファイルシステムやデータベースなどの記憶手段の他、計測結果を利用するAP(たとえば常駐型プログラム)であっても良い。

【0024】なお計測操作部12、計測情報ブローカー11 0、計測部131、計測対象132、出力先14はマシンを分け る必要はなく、同一のマシン上に複数の機能が共存して いても良い。

【0025】1.2 ハードウェア構成

図1中の本構成要素が実装される機器20は、図2に示す適か、CPU211、メモリ212、キーボード213、ディスアレイ214、ハードディスクドライブ215、ネットワーク222などによって実現する。なお、これらのハードウェア都品のすべてが必要なわけではなく、必要に応じて省略しても良い。たとは、ある機器210が人とのインターフェイスを必要としないなら、キーボード213やディスアレイ214を省略できる。

【0026】1.3 計測情報ブローカーの概要 本発明の主体である計測情報ブローカー110について以 下説明する。

【0027】(1)計測情報ブローカーの構成

図3は計測情報プローカー110の構成要素と他との関係を示したものである。 【0028】計測情報プローカー110は、計測タスク登

鉄部11、計測手段選択部112、計測指示部113、計測結 果収集部114、計測結果出力先選択部115、計測結果出力 部116、計測情報ブローカー管理部117から成る。

【0029】(2)計測情報プローカーの処理手順 図4のフローに従って、計測および計測結果の収集、出力を行う際の手順を示す。

【0030】計測操作部2から計測情報プローカー管理 部117に計測指示が出されると(図4の4101)、それが 計測タスク登録部111に伝達される、そして、計測手段 選択部12で前記計測指示の内容に基づいてどの計測機 能を計測に当たらせるかを選択し、図4の4102)、計測機能13 に計測指示を出す(図4の4103)。計測機能131は計測 指示部13から受けた計測指示に基づいて計測対象132の 指示部13から受けた計測指示に基づいて計測対象132の 計測を行い、計測機能31に対応した計測結果収集部114 に計測結果収集部114 に計測結果収まる。計測核単印集部114は計測結果収集部114 行致ると (図4の4104) 計測結果を計測情報プロカ -110内で使われる結果の標準形式に変換する (図4の4 105) 。そして、計測結果出力選択部15で3機構果の出 力先を選択する (図5の4106) 。出力先の選択は、前記 計測操作部12から計測情報プローカー管理部117に出さ れた計測特示に基づいて行う。最後に選択された出力先 に対して、計測結果出力第116を用いて計測結果出力先1 4を計測結果と出力する (図4106)。

【0031】2. 計測情報ブローカーの詳細 以下、1.3節(1)で述べた構成要素毎に詳細を示す。

【0032】2.1 計測タスク登録部

計劃に時間かかかる場合や、計劃操作部12が複数存在するなどの状況に対応するため、本実施例では複数の計測 処理を同時に実行できるようにする。図4のフローで示した。通り、本発明では、計劃の指示、計測結果の収集、 計測結果の出力を含む一連の計測手順を実行するが、こ の計測手順を計測タスクと呼ぶことにする。

【0033】(1)計測タスク定義情報

図4のフローの4101で示したように、計測処理の実行に あたって、計測接件部12から計測クスクの実行に必要な 情報を受け取るが、この情報を計測クスク定義情報310 と呼ぶ。計測クスク定義情報310の内容は、図5に示し た通り、計測内容3110、計測結果収集方法3120、計測結 果出力方法3130の三つによって構成すれば良い。

【0034】計測内容31102計測対象31112とび計測項 目3112を含み、図4のフローの4102および4103で必要と 公針計劃機能の選択および計画実行の際に参照される。 【0035】計測結果収集方法3120は、一回の計測だけ でなく開期的な計測を実現するためのものであり、計廻 時期3121、開始日時3122、終了日時3123、計測周期3124 会をは、計画時期3121は、計測が一回だけのものか、周 期的に繰り返すものかの別を示すフラグである。計測が 周期的に繰り返すものかの別を示すフラグである。計測が ら始めるか(開始日時3122)、いつ終わるか(終了日時 3123)とのような周期で計測を繰り返すが、計測周期 3123)と指定する。なは、計測が一回だけの場合でも開 始日時3122を指定する。ことで、指定日時に一度だけ計劃 できるようにしても良い。

[0036] 計測結果出力方法3130は、図40フローの 4106および4107の処理の際に参照され、計測結果出力方 法3130は、出力先個数3131、および出力先個数3131で指 定された個数の出力先31320を含む。出力先31320は、さ らに出力先の種類31231、出力先の I D31322、出力項目 31323、符号化方式31324によって構成される。これらの 詳細については、2、5節3よ1572、6節で強べる。

【0037】(2)計測タスクプール

複数の計測タスクを同時に実行するために、実行中の全 計測タスクに関する情報を保持する必要がある。その計 測タスクの保持手段をタスクプール320と呼ぶことにす る。タスクアール320のデータ構造は図6に示すよう に、タスク情報3210が展列された形にすれば良い。タス ク情報3210の内容は、タスク1D3211、タスクの要求元 3212、計測タスクの定義情報310、タスクの進捗状況321 30、タイムスタンプ32140を含む。

【0038】タスク I D3211は複数の計測タスクを一意 に識別するための識別子であり、計測タスク登録時に既 存の計測タスクと重複しない値を設定すれば良い。 【0039】タスクの要象元3212は計測タスクの登録者

ものもライスの表示におより、 を示す情報であり、計測結果を計測タスクの登録者に対 して出力する場合に、複数の計測操作部12のどこに返せ ば良いのかを計測結果出力部116が知るためなどに用い る。

【0040】計測タスク定義情報310は、前述した計測 操作部12から指定された計測タスクに関する定義情報で ある。

【0041】タスクの進捗状況32130は、計測タスクの 処理がどこまで進んでいるかを示すものであり、タスク 終了フラグ3213、計画の進捗32132、出力の進捗32133 を含む。これらの情報は計測タスクの進捗状況を確認す る場合などに用いる。

【0042】タイムスタンプ32140は、計測タスクの処理に関する日時を記録しておくためのものであり、タスクの作成日時3214、計測日時32142を含む。これらの情報は、計測タスクや計測結果の鮮度を知るためなどに用しな

【0043】2,2 計測手段選択部

計測タスク定義情報310に含まれる計測内容3110は、計 湖内第3111と計測項目3112によって計測内容を指定させ るようになっており、そこには計測機能313の種類を指 定させない。これは、計測情報プローカーの利用者に計 測限能の詳細を意識させない、指象化する)ことによっ で計測に関する検定をより容易しするためである。

【0044】ただし、実際に計測を行う際には、どの計 測機能131を利用するかを決定する必要があるため、計 測内容31100指定内容から計測機能の種類を導き出す必 要がある。その変換を行うための情報が、計測機能対応 表330である。

【0045】(1)計測機能対応表330のデータ構造 計測機能対応表330は図7に示すように、対応情報3310 の羅列の形を取る。さらに対応情報3310は計測内容311 (、計測機 I D3311、計測方法 I D3312、計測項目 1 D3 313からなる。

[0046] 計測内容31104計測タスク定義情報30に含まれるものと同じである。計測機 I D33114計測内容 3110に対応した計測機能と有するマシンの式則をであり、たとえば「Pアドレスが入る。計測方法・D33124計測方法の種類に関する談別をであり、たとえば「SAP//MM/J、や「CII//MII」などが入る。計測項目 I D3313 と計判測なる。

ェクト名やCIMのインスタンス名などが入る。

【0047】計測情報プローカー110内に計測機能対応 表330をあらかじめ定義しておくことで、計測内容5110 の内容に応じて適切な計測方法、計測機能131を選択で きるようになる。

【0048】(2)計測機能対応表330の例

図名に計測機能対応表33の例を示す、データの一行目 の意味は次の通りで、他の行も同様な解釈を行う。「se rver_l」の「Cドライブの空き容量」を計測するには、 「server_l」に対して「CIM/WMI」の計測方法で「Win3 2_logicalDisk,DeviceID=" C:" のインスタンスのFreeS pacc属性」を影響する。

【0049】このように、計測機能対応表330による変 換を行うことで、計測機131の種類に依存しない表現 で、計測内容310を指定できる。

【0050】なお、計測機能が成表330を使用せず、計 測タスク定義情報310内で直接計測機 I D3312、計測方 よ I D3312、計測項目 I D3312を指定するようにしても 良い。このようにした場合、計測機能対応表330に計測 項目を登録する手間を省略できる(ただし、計測タスク の登録の際、実践に近いレベルの情報入力が必要とな り、計測タスタの登録作業が頻馏となる)。 計劃タスタの登録作業が頻馏となる)。

【0051】(3)複数指定

一つの計測タスクで一つの計測内容を処理することが基本だが、同様な計測を繰り返す場合。計測タスクの個数が増えるため、計測タスクの処理に要するオーバーヘッドが気になる。そのため、一度の一つの計測タスクで複数の計算対象、計測項目を処理するようにしても良い。 (0052) たとえば計劃対象:311の指定で、複数の計測結果おるいは測定値の合計値や平均億を返すことが考えられる。また、複数の対象を併記する代わりにアスタリスクキタエスチョンマークなどのメタキャラクタを利用することも考えられる。たとえば、アスタリスクのみを選択すると指定した計測項目3112の計測が可能なポットワーク内のすべての機器に対して計測の目的をなポットワーク内のすべての機器に対して計測を行うなどの適用が考えられる。

【0053】また、計測項目3112内に複数の計測項目を 併記することで複数の計測を行うことも考えられる。

【0054】なお、計測対象および計測項目が複数になると計測結果も複数になることが考えられるが、その場合、複数の計測結果をそのまま返すか、平均値あるいは、合計値を返すなど(測定結果が数値データの場合)を行えば良い。

【0055】2.3 計測指示部

として計劃を指示する。たとえば、図8の一行目の情報を処理する場合、「server_1」に対して、「CIM-VMI」のインターフェイス(API)を用いて、「Min32_LogicalDeviceID="C:"」のインスタンスの同い合わせ(クエリー)を発行する(そして、返ってきた結果の「Free Soace」版件を計劃結果とする)。

【0056】計測指示部113の実装の際には、利用する 計測方法の種類に応じて計測時示部115名用意する形を 取れば良い。たとえば、CIM用計測指示部、ping 用計測指示紙、SNMP用計測指示部など専用モジュー ル化する。また、計測手段選択部112と計測指示部113間 のインターフェイスを核一することで、計測括示部113 の実装および計測指示部113の実装がよび計列指示部13のの実法がよび計測指示部113の (2. 7節(3)参照)。

【0057】(1)カスタムプログラム

計測指示部13の機能(計測機能対応第390の計測方法] D3312で規定される計測方法)は、計測部33への構造 とをするもの 以下、構造(シイブ)に限定されない。 それは、より高度な計測結果を得るために、複数の計測 処理を実施し、分析を行うようなカスタムプログラムで あっても長い。

【0058】たとえば、SNMPで得られる情報とC1 Mで得られる情報を総合的に分析することが必要な場合。計劃操作部12からそれらの計測タスクを個別に定義し、実行させ、得られた結果を分析するといった処理が必要になる。計測項目が少ない場合、計測項目の20年間別なに定義し実行することも考えられるが、計測項目が20年間別数になると計測ゲスクの実行に要するオーバーヘッド(計劃操作部12と計測情報プローカー110世の計測タスク処理、計測情報プローカー110上のの計測タスク処理、対測情報プローカー110と出力先出側の通信トラフィック。をとのオーバーヘッド)が大きくなる。

[0059] そこで、カスタムアログラムによって一種 のマクロ機能を提供し、一つの計測タスクを実行するこ とで複数の計測処理を実行し、それらの計測結果を分析 した上で、必要な結果のみを出力先14へ出力するように すれば、前記計測タスク多数発行する際のオーバーへ ッドを軽数できる。

[0060] カスタムプログラムは、通常の計測指示部 13の機能(SNMPやCIMなどに対応した計測部31 への機能しをするタイプの計測指示機能)と同様に計測 タスクから呼び出せるように、計測機能対応表330で定 義可能にすれば良い(計測方法ID3312でSNMPやC IM、カスタムプログラムの機能を区別)、

【0061】なおカスタムプログラム内で他の前記橋渡 レタイプの計測指示部113や他の(あるいは同じ)カス タムプログラムを呼び出せるようにしても良い。

【0062】2.4 計測結果収集部 計測結果収集部114の働きは、計測結果の収集と計測結 果の整形である。

【0063】(1)計測結果の収集

図3では計測指示部113と計測結果収集部114を分けて記述しているが、実際には計測指示と計測結果の収集は一体であることが多い。たとえば、SNMPやC1M、pingの実存などでは計測指示(問い合うセ発行)を行った際の戻り値が計測結果となる。ただし、計測に時間がかかる等の理由で、計測指示と結果収集が同間期に行われることも考えられ、その場合、計測指示部113と計測結果収集が14は収収率となる。

【0064】計測結果収集部114は通常、計測指示部113 と同様、計測方法の種類に応じて用意することになる (SNMP用、CIM用、ping用など)。

【0065】(2)計測結果の整形

計測機能131から送られた情報(計測結果)をそのまま 計測情報プローカーの計測結果とするのではなく、計測 機能131から送られた情報を加工すると良い。情報の加 工には、余分なデータの削除、補足情報の追加、計測結 果の形式の結一がある。

【0066】(2)-1 余分なデータの削除

計測機能31から送される計測結果に余分をデータが含 まれている場合、それを取り除かなければならない。 たとえば、ネットワークの応認時間を測定する目的でpi ngを実行したとしても、pingの実行結果には、p ingの気光のアドレスや説明ななども含まれており、 これらは測定の目的と関係ないものである。

【0067】(2) - 2 相足情報の追加:計測した情報に計測した時のタイムスタンプを追加しても良い。 電のことによって、計測結果の軽度を識別しやすぐなる。 【0068】(2) - 3 計測結果の終度を識別しやすぐなる。 【0068】(2) - 3 計測結果の形式の統一:計測 機能131の種類によって計測機能131から送られる結果の 特報が式は異なる。たとえば、SNMPとCIMでは異なるし、pinsも同様である。そのため、計測結果収 集部114から計測結果出力部116に渡す情報の形式が、計 結果出力部を用意しなければならなくなる。これを避け るために、計測結果収集部114から計削結果以力部116で、 また者が表したで、新 なす情報を使した方が良い、またそうすることで、新 しい計測機能131に対応する計測結果収集部114を後で追 加する原にも、計測結果以力部116を変更する必要がな くなら(2,7m(3) 参照)

【0069】2.5 計測結果出力先選択部

計測結果出力先選択部115は、計測タスク定義情報310内 に含まれる計測結果出力方法3130の内容に基づいて、計 測結果収集部114で収集した計測結果の出力先を選択す るものである。計測結果の出力先として、たとえば以下 の物が考えられる。

【0070】(1)計測タスクの登録者

計測結果を計測タスクの登録者に返す。たとえば、ある 計測操作部12のコンソールから計測タスクを登録した場 会 そのコンソールに返す(画面トに表示する)など。 計潮タスクの登録者がアプリケーションの場合も、同様 にそのアプリケーションに返す。

【0071】(2)ファイル/データベース

計測情報プローカー内あるいは他のマシン上の共有ディ レクトリに計測結果を出力する。周期的に計測を行う場合は、一つのファイルに追記していくことで記録することでログファイルを形成する。データベースについてもファイルと同様。

【0072】(3) アプリケーションや通信ボートへの 出力

計測情報プローカーが稼動しているマシン上またはそれ 以外のマシン上に存在するアアリケーション(CORB AやDCOMなどの分散オブジェクトを含む)や通信ホ ート(シリアルボート出力、SNMPトラップなどのイ ベント送信など)に対して計測結果を出力する。

【0073】これら三つの方式の使い分けについて補足 する。(1) は標準的な使い方であり、コンソール画面 上で計測純果を確認したい場合に向く。(2) は情報の 提供者主導で情報の受領者に情報を送信するという、い かゆるPush型の送信となるため、計測結果の送信に即時 性が求められる場合に使えば減い。また(3) は情報の 受け取り手上導で情報を取りにいくという。いわゆるPu 1型の情報転送となるため、多数の情報利用者で同一の 計測結果を失寿する場合に用いば貸い。

【0074】当然のことながら、一つあるいは複数の計 測タスクに対し、複数の計測結果出力方式を併用しても まったく問題ない。

【0075】2.6 計測結果出力部

計測結果出力部116は、計測結果収集部114で処理した計 測結果を計測結果出力が北に出力する機能を持つ。2.5 5節で述べた計測結果の出力先のタイプ (ファイル、デ タペース、アプリケーション、通信ボートなど) に対 応した処理機能を用意すれば長い。

【0076】なお計測情報プローカー内に計測結果専用 の記憶領域を確保し、そのデータベースに他のマシンか らアクセス可能にすることで、計測結果を複数のマシン (情報利用者)で共有できるようにしても良い。その記 憶額域(計測結果格納庫)の例を図9に示す。

【0077】(1)計測結果格納庫

計測結果格納庫30は測定結果3410のリストになってお り、測定結果3410はさらにタスク I D3211、インターバ ル計測技番3411、計測タスク定義情報310、タイムスタ ンプ3240、計測結果3412で構成する。

【0078】計測結果1D3411と計測結果技務312は、 計測結果を一意に説別するためのものであり、計測結果 を登録する際に他の計測結果3410で指定されている内容 と重複しない名前(または番号等)を付与すれば良い。 計測結果の1Dを二種類用意した理由は、前希を計測タ スク1D3211に、後者を一つの計測タスクで複数回の計 測を行った際(開期的な計測などによって添生)のシー ケンス番号に、それぞれ割り当てることを想定したため である。こうすることで、計測タスクと計測結果の対応 関係を表現できる。もちん計測結果技養3412を省略 し、計測結果1 D 3411のみで計測結果を餞別する形にし ても問題はない。

【0079】計測タスク定義情報310は、その計測結果 を得るために使用した計測条件である。この項目は特に 必要ない場合、省略しても良い。

【0080】計測日時32142は、計測結果の鮮度を知る ための特報として、計測を行った日時を格納する。 (0081】計測結果3413は計測結果の格納エリアであ る。

【0082】なお計測結果格納庫340はファイルシステム上あるいはデータベース上に実装すれば良い。

【0083】2.7 計測情報ブローカー管理部 計測情報ブローカー管理部117では、計測情報ブローカ ー110内の各種管理を行う機能を有する。

【0084】計測タスタの実行を含む計測情報プローカ 一のシステムの管理全般を行う。管理項目は、計瀬タス クの管理、計測機能対応表の管理、各種モジュールの管 理、計測結果格納庫の管理の四つである。

【0085】人手による管理が必要な管理作業については、計算操作部12にコンツールを持たせ、そのコンソール画面上で各種管理内容を指示できるようにすれば良い、図10は、計測操作部12のコンソール上と表示される計測情報プローカー管理部117の管理第42によりであり、前述した計測情報プローカー管理部117の管理項目に対応したボタン(5011~5014)と表でオシン5015を備えている。各ボタンを押す(選択する)ことで、各管理項目(画面)に移行する。

【0086】以下、計測情報ブローカー管理部117が処理する四つの管理項目(前述)について説明する。

【0087】(1)計測タスクの管理

計測タスクはタスクアール320に登録され、実行される ため、計測タスクの管理はタスクアール320の管理と言 い検えることができる。タスクアール320の管理項目と しては、計測タスクの新規登録、タスクアール320内に 登録されている計測タスク(タスク情報3210)の削除、 内容変更などがある。

[0088]計測タスクの新規登録は、2.1節で述べ た通り、タスクアール320へのタスク情報の追加登録す あ形で実現する。また、タスクアール320内の計測タス クの削除は、タスクアール320内に登録されている特定 のタスク情報を削除する形で実現する。計測タスクの内 容変更についてもそれらと同様に、タスクアール320内 のタスク情報を変更する形で対応する。

【0089】(1) -1 計測タスク管理画面 図11は計測タスク管理画面の20である。計測タスクの - 覧5021はタスクプール内に存在するタスク情報の一覧 を表示しているもので、反転表示されている存はそのタ スク情報が現在選択されていることを示している。

[0090] 新規ボタン5022は計測タスクを新規登録する際に押すボタンで、このボタンを押すことにより、計 測タスク設定画面A5030に移行して計測タスク定義情報 310相当の情報を入力した後、その入力内容をタスクプ ールに登録する。

【0001】詳細ボタン5023を押すと選択されているタスク情報の詳細情報を表示し、削除ボタン5024を押すと選択されているタスク情報を削除する。閉じるボタン502を押すと、計測タスク管理画面を終丁し、管理メニュー画面が010に戻る。

【0092】(1)-2 計測タスク設定画面A

図1 2は計測タスク設定画面A5030を示したもので、計 測タスクの計測方法に関する設定項目を入力するために 用いる。

[0093]計測機能以定網の32で設定する内容は、計 潮タスク定義情報310内の計測内容3110に相当するもの である。同様に、計測方法設定機5033で設定する内容 は、計測タスク定義情報310内の計測結果収集方法3120 に相当するものである。その他、出力方法ク75041を押 す(選択する)ことで計測タスク設定画面 Bに移行する。また、0 K ボクン5034を押すことで設定内容を保存 (タスクプール内に登録)して計測タスクの管理画面 (メイン)5020に移行し、キャンセルボタン5035を押す ことで設定内容を保存しないて計測タスクの管理画面 (メイン)5020に移行する。

【0094】(1)-3 計測タスク設定画面B

図13は計測タスク設定画面B5040を示したもので、計 測結果の出力方法に関する設定項目を入力するために用 いる。

[0095]出力先一覧5042は当該計画タスク用に設定されている出力先の一覧である。本実施例では、計測タスク定義情報の出力先31520を教験所でる (80参照)ため、設定画面も複数の出力先指定に対応できるようになっている。出力先一覧5042の一行が計測タスク定義情報30の出力を3320一つ分を用当する。

[0096] 追加ボタン5043を押すことで、計測タスク 設定側面で5050に移行し、出力先を追加する。まな、詳 継ボタン504を押すことで、計測タスク設定面面で5050 に移行し、出力先一覧5042内で選択されている出力先の 設定内容の変更を行う。そして、削除ボタン5045を押す ことによって出力先一覧5042内で選択されている出力先 を削除する。

【0097】その他、計劃方法タブ5031を押す、選択する)ことで計劃タスク設定順面Bに移行する。また、0 ボオク5046を押すことで設定内容を保む(タスクアー ル内に登録)して計測タスクの管理画面(メイン)5020 に移行し、キャンセルボタン5046を押すことで内容を保 存しないで計測タスクの管理画面(メイン)5020に移行 する 【0098】(1)-4 計測タスク設定画面C 図14は計測タスク設定画面C5050を示したもので、計 測タスクの計測結果の出力方法に関する設定項目を入力 するために用いる。

[0099]出力先設定標5051で設定する内容は、計場 タスク定義情報310内に含まれる出力先の種類1312と出 力先の103132に相当するものである。また、出力内 容設定欄5052で設定する内容は、計測タスク定義情報31 0吋に含まれる出力項目31323に相当する。同様に、符号 化設定欄5053で設定する内容は、計測タスク定義情報31 0吋に含まれる符号化方式31324に相当する。

【0100】その他、OKボタン5054を押すことで設定 内容を保存(タスクプール内に登録)して計測タスク設 定画面 B5040に移行し、キャンセルボタン5055を押すこ とで設定内容を保存しないで計測タスク設定画面 B5040 に移行する。

【0101】(2)計測機能対応表の管理

計測機能対応表330の管理項目は、計測機能対応表330内 に含まれる対応情報3310の追加・変更・削除である。

【0102】図15は計測機能対応表管理画面5660を示 したものである。対応情報一覧5051では、対応情報のリ ストが表示されており、一行が対応情報3310一つ分に相 当する。

【0103】 通加ボタン5052を押すことで対応情報3310 を追加する。また、変更ボタン5053を押すことによって 対応情報一覧5051内で選択されている対応情報3310に関 して設定の変更を行う。そして、削除ボタン5054を押す ことによって対応情報一覧50501内で選択されている対 応情報3310を削除する。関じるボタン5055を押すことで 計測機能が応表の管理画面(メイン)5060を終了し、管 理メニュー画面5010に戻る。

【0104】(3)各種モジュールの管理

さまざまな計測手法や出力形式に対応するためには、計 測指示部113、計測結果収集部114、計測結果出力部116 をモジュール化すると良い。

【0105】図16は計測情報プローカー110が利用可能なモジュールに関する情報を記録するモジュールに襲まる特徴を記録するモジュール定義表350であり、モジュール定義3510はさらに識別名3511、機能タイプ5512、モジュールの実体3513から成っている。

[0105] 総別名5511は、計測機能対応約330内の計 部方法 I D3312と、あるいは計測タスク定義情報310内 の出力先の機類3131と、対応関係にあり、計測方法 I D3312あるいは出力先の機類31321で指定された内容 モジュール (の実体と) を結び付けるためにある。機能 タイプ5512は至ジュールの機能の種類(計測、収集、出 力の別) を示す情報である。モジュールの実体3513は、 モジュールの実体を指し示す情報(アログラムコードの 格納先やオブジェクト名など)である。

『OIO7】図17はモジュール管理画面である。モジ

ュール一覧5071は、計測情報ブローカー110上に登録されているモジュールの一覧を示しており、一行がモジュールの一覧を示しており、一行がモジュール一個分の定義になっている。

【0108】追加ボタン5072を押すことでモジュールを 追加する。また、変更ボタン5073を押すことによってモ ジュール一覧50710内で選択されているモジュールに関 する設定の変更を行う。そして、削除ボタン5074を押す ことによってモジュール一覧50710内で選択されている モジュールを削除する。関しるボタン5075を押すことで 計測機能が放表の管理画面(メイン)5070を終了し、管 理メニュー両面5010に戻る。

【0109】(4)計測結果格納庫の管理

計測結果格納庫340の管理項目は、同格納庫内に登録されている計測結果3410の内容表示や削除である。

【0110】図18は計瀬結果格納麻管理画面5080を示 したものである。計瀬結果一覧5081は、計瀬結果格 納庫340内に登録されている計瀬結果の一覧を表示す るもので、一行が一回の計瀬に相当する。

[011] 詳細ボタンの82を押すことにより、計測結果 果一覧281内で選択されている計測結果3410の内容を表示する。また、削除ボタン5032を押すことにより、計測 結果一覧2081内で選択されている計測結果3410を削除す る。そして閉じるボタン5084を押すことで計測結果格約 面で3010に戻る。 面で3010に戻る。

[0112]

【発明の効果】以上のように、本発明によれば、計測機能に依 辞を必要とする管理アプリケーションは、計測機能に依 存したアクセス手段を用いること無く、単一のアクセス 手段によって計測情報を受け取ることができる。このこ とによって、計測情報を対けなるとができる。このこ の開発もよびタステムへの実装が容易になる。

【0113】また、計測結果を計測情報プローカー内に 保持したり、計測情報を要求した者以外の対象へ計測結果 果を出力(送信)したりすることで、計測結果を複数の 計測情報利用者(管理アプリケーション)間で共有する ことが容易になる。

【図面の簡単な説明】

【図1】本発明の実施形態に係るシステムの構成を示す ブロック図である。

【図2】本発明の実施形態に係る計測操作部、計測情報 ブローカー、計測結果出力先、計測機能、計測対象ハー ドウェア構成のハードウェア構成を示すブロック図であ る。

【図3】本発明の実施形態に係る計測情報ブローカーの 内部構成を中心としたブロック図である。

【図4】本発明の実施形態に係る計測情報ブローカーの 処理フロー図である。

【図5】本発明の実施形態に係る計測情報プローカーで 処理される計測タスク定義情報の内容を示す図である。 【図6】本発明の実施形態に係る計測情報ブローカーが 保持するタスクプールの内容を示す図である。

【図7】本発明の実施形態に係る計測情報ブローカーが 保持する計測機能対応表の内容を示す図である。

【図8】本発明の実施形態に係る計測情報ブローカーが 保持する計測機能対応表の内容例を示す図である。

【図9】本発明の実施形態に係る計測情報ブローカーが 保持する計測結果格納庫の内容を示す図である。

【図10】本発明の実施形態に係る計測操作部上に表示される管理メニュー画面の表示例を示す図である。

【図11】本発明の実施形態に係る計測操作部上に表示

される計測タスク管理画面の表示例を示す図である。 【図 1 2 | 本発明の実施形態に係る計測操作部上に表示 される計測タスク設定画面 A の表示例を示す図である 【図 1 3 | 本発明の実施形態に係る計測操作部上に表示 される計測タスク設定画面 Dの表示例を示す図である。

【図14】本発明の実施形態に係る計測操作部上に表示


される計測タスク設定画面Cの表示例を示す図である。 【図15】本発明の実施形態に係る計測操作部上に表示 される計測機能対応表管理画面の表示例を示す図であ ス


【図16】本発明の実施形態に係る計測情報プローカー が保持するモジュール定義表の内容を示す図である。 【図17】本発明の実施形態に係る計測操作部上に表示 されるモジュール管理画面の表示例を示す図である。 【図18】本発明の実施形態に係る計測操作部上に表示 される計測結果格构庫管理画面の表示例を示す図である。 る。

【符号の説明】

110・計測情報プローカー、111・計測タスク管理部、11 2・計測手段選択部、113・計測指示部、114・計測結果 収集部、115・計測結果出力先選択部、116・計測結果出 力部、12・計測操作部、131・計測機能、132・計測対 象、14・計測終集出力先

計画タスタ





[図8]


図 8


計測機能対応表の例

計劃項目	計劃対象	計測機(D	計測 方法ID	計測項目ID
Cドライブの空き容量	server_1	server_1	CIM /WMI	Win32_LogicalDisk.DeviceID="C:" FreeSpace
ネットワークI/Fの応答時間	servor_1	localhost	CMD/ ping	average time
ネットワークセグメント内で 受信されたパケット教	123.45.67	123.45.67.99	SNMP /RMON	1.3.6.1.2.1.16.1.1.1.5 (etherStatsPkts)
	:	:	:	:


[図10] (図11] 図10 図11 智利/ニュー編集 計画なみで物理機能












(03)102-157172(P2002-157172A)

【図18】

図 18

計測結果推納單管項面面



Machine Translation of JP 2002-157172

* NOTICES *

JPO and INPIT are not responsible for any damages caused by the use of this translation.

- 1. This document has been translated by computer. So the translation may not reflect the original precisely.
- 2.**** shows the word which can not be translated.
- 3.In the drawings, any words are not translated.

DETAILED DESCRIPTION

[Detailed Description of the Invention]

[0001]

[Field of the Invention] This invention relates to the information gathering about the operation and the engine performance of various resources which exist on the network/system in the distributed computing environment which two or more computers are connected by a computer system, especially the network, and is used. [0002]

[Description of the Prior Art] In order to employ and maintain the computer system, it is required to supervise actuation of the element function which constitutes a system. Prediction of the engine performance and capacity which will be needed the early detection of the abnormalities in a system and in the future etc. is attained by monitoring continuously whether it is working normally or it is not an overload.

[0003] The main functions for realizing a monitoring function are an information collection function and a measurement function. Required measures will be taken, if normal/abnormalities are judged and abnormalities or the indication connected unusually can see, after acquiring the operation situation check result for a monitor, the measurement result of a load, etc.

[0004] Each device itself may have a means to collect information from the configuration equipment in a network/system, and it has a device, a tool, etc. only for measurement. However, the access means against those information collection functions changes with classes of device rather than is uniform.

[0005] For example, in the case of a network device, there is SNMP (Simple Network Management Protocol) specified as a standard protocol for network administration in IETF (Internet Engineering Task Force), but there is WBEM (Web-based Enterprise Management) specified by DMTF (Desktop Management Task Force) as an interface for computer management.

[0006] In the device of the still more nearly same class, an access means is not necessarily one, either. For example, in the case of the network device, it has the access means of a network device vendor proper other than the above-mentioned SNMP in many cases. And as for the ability of a more advanced function to be pulled out, it is common that it is the latter.

[0007] Moreover, there are also a monitoring function/an information collection function only for software in software. For example, about the operation and performance monitoring about the application software which operates on a computer, it is The. Open

There is an interface called ARM (Application Response Management) which is the standard specifications upon which it was decided by Group.

F00081

- [Problem(s) to be Solved by the Invention] Many [as the conventional technique described / operation of the element function within a computer system, or the class of access means against the information collection function about the engine performance In order to access these information collection functions conventionally, the side (management application side) using an information collection function needed to prepare the logic corresponding to the access means according to individual, and the development burden of application and the burden on mounting to a system were large. [0009] This invention aims at mitigating these burdens.
- [0010] In addition, this invention relates to the measurement processing and information gathering processing for various monitoring function implementation. Although the expression "measurement" is used below in the text, it is the semantics of information gathering required for various monitor and managements.

- [Means for Solving the Problem] In order to solve said technical problem, by this invention. I/F of the proper to a measurement function is concealed by using the measurement info broker who executes information gathering processing to a measurement function by proxy.
- [0012] A measurement info broker's component has the following components, and the application (management application) which needs measurement information is provided with a single access window.
- [0013] (1) The function to receive a demand of the measurement information published from measurement demand reception feature application.
- [0014] (2) The function which chooses the access means to a measurement function according to the content of the measurement means optional-feature aforementioned demand.
- [0015] (3) The function to publish measurement directions to a measurement function by the access approach corresponding to a measurement directions functional measurement function
- [0016] (4) The function to collect measurement results from a measurement result collection functional measurement function.

[0017]

- [Embodiment of the Invention] 1. It is the output destination change 14 the measurement control unit 12, the measurement info broker 110, the measurement function 131, and for [132] measurement, and they are connected by the network 22 as the component of the whole system of whole system configuration this invention is shown in drawing 1. [0018] In addition, although drawn at drawing 1 in the form which exists on another device 210 by which each component was separated by the network 22, two or more components may be mounted on the same device 210. For example, the measurement control unit 12 and the measurement info broker 110 may be mounted on the same device 210. Moreover, it is not necessary to necessarily connect with the network 22, and the object 132 for measurement should just be in a condition measurable from the measurement function 131.
- [0019] 1.1 The functional description measurement control unit 12 of each part has the

function to publish the directions about various actuation of the measurement info broker 110, to the measurement info broker 110. In addition, the measurement control unit 12 assumes the terminal (console) and application (local/remote application) of the measurement info broker Management Department 117 accessible to a function. [0020] The measurement info broker 110 is the subject of this invention, and has the function to perform the measurement directions to the measurement section 131, and transmission to the output destination change 14 of a measurement result based on the directions from the measurement control unit 12. The measurement info broker's 110 detail is given with "2. a measurement info broker's detail."

[0021] The measurement function 131 measures the object 132 for measurement based on the directions from the measurement info broker 110, and has the function to pass the measurement info broker 110 a measurement result. In addition, measurement function 131 the very thing does not need to have a measurement function, and may be a junction function to still more nearly another measurement function.

[0022] The object 132 for measurement is an object of measurement, and is measured by the measurement section 131. The object 132 for measurement may be the firmware or software which works on a device besides hardware, such as a network, and router equipment, a computer apparatus.

[0023] An output destination change 14 is an output destination change of a measurement result. You may be AP (for example, resident mold program) using a measurement result besides storage means, such as a file system and a database.

[0024] In addition, the output destination change 14 the measurement control unit 12, the measurement info broker 110, the measurement section 131, and for [132] measurement does not need to divide a machine, and two or more functions may live together on the same machine.

[0025] 1.2 CPU211, memory 212, a keyboard 213, a display 214, a hard disk drive 215, a network 222, etc. realize the device 210 by which each component in hardware configuration <u>drawing 1</u> is mounted as it is shown in <u>drawing 2</u>. In addition, not all these hardware components are required reasons, and it may omit if needed. For example, if a certain device 210 does not need an interface with people, a keyboard 213 and a display 214 are omissible.

[0026] 1.3 Explain below the measurement info broker 110 who is the subject of a measurement info broker's outline this invention.

[0027] (1) A measurement info broker's <u>block diagram 3</u> shows the relation between the measurement info broker's 110 component, and others.

[0028] The measurement info broker 110 consists of the measurement task registration section 111, the measurement means selection section 112, the measurement directions section 113, the measurement result collection section 114, the measurement result output destination change selection section 115, the measurement result output section 116, and the measurement info broker Management Department 117.

[0029] (2) According to the flow of a measurement info broker's procedure <u>drawing 4</u>, the procedure at the time of performing measurement and collection of a measurement result, and an output is shown.

[0030] If measurement directions are taken out from the measurement control unit 12 to the measurement info broker Management Department 117 (4101 of <u>drawing 4</u>), it will be transmitted to the measurement task registration section 111. And it chooses which measurement function is made in charge of measurement based on the content of said measurement directions (4102 of drawing 4), and measurement directions are taken out with the measurement means selection section 112 to the measurement function 131 using the measurement directions section 113 corresponding to the measurement function 131 (4103 of drawing 4). The measurement function 131 measures the object 132 for measurement based on carrier beam measurement directions from the measurement directions section 113, and returns a measurement result to the measurement result collection section 114 corresponding to the measurement function 131. The measurement result collection section 114 will change a measurement result into the standard format of the result used within the measurement info broker 110, if a measurement result is received (4104 of drawing 4) (4105 of drawing 4). And the output destination change of a measurement result is chosen in the measurement result output selection section 115 (4106 of drawing 5). Selection of an output destination change is performed based on the measurement directions taken out from said measurement control unit 12 to the measurement info broker Management Department 117. A measurement result is outputted to the measurement result output destination change 14 to the output destination change chosen at the end using the measurement result output section 116 (drawing 4106).

[0031] 2. A detail is shown below a measurement info broker's detail for every component stated with Section 1.3 (1).

[0032] 2.1 Since the case where measurement task registration section measurement takes time amount, and the measurement control unit 12 correspond to the situation of more than one existing, enable it to perform two or more measurement processings simultaneously in this example. Although a series of measurement procedures including directions of measurement, collection of a measurement result, and the output of a measurement result are performed in this invention as the flow of drawing 4 showed, this measurement procedure will be called a measurement task.

[0033] (1) Although information required for activation of a measurement task is received from the measurement control unit 12 in activation of measurement processing as 4101 of the flow of measurement task definition information drawing 4 showed, call this information the measurement task definition information 310. What is necessary is for three, the content 3110 of measurement, the measurement result collection approach 3120, and the measurement result output method 3130, just to constitute the content of the measurement task definition information 310 as it was shown in drawing 5.

[0034] The content 3110 of measurement is referred to including the measurement item 3112 for [3111] measurement in the case of selection of the measurement function which is needed by 4102 and 4103 of the flow of drawing 4, and measurement activation.

[0035] The measurement result collection approach 3120 is for realizing not only one measurement but periodic measurement, and contains the measurement stage 3121, the initiation time 3122, the termination time 3123, and the measurement period 3124. The measurement stage 3121 is a flag with which measurement shows the exception of 1 time of a thing, and the thing repeated periodically. When measurement is what is repeated periodically, it specifies when it finishes or (termination time 3123) what kind of period measurement is repeated [from when the measurement is begun, or] (measurement period 3123). (initiation time 3122) In addition, you may enable it to measure only at

once in assignment time because measurement specifies the initiation time 3122 also by 1 time of the case.

[0036] The measurement result output method 3130 is referred to in the case of 4106 and processing of 4107 of the flow of drawing.4 and the measurement result output method 3130 includes the output destination change number 3131 and the output destination change number 3131. An output destination change, mailto:drawing. The further constituted by the class 31321 of output destination change, mailto:drawing. moutput destination change, an output item 31323, and the coding method 31324. These details are given with Section 2.5 and Section 2.6. [0037] (2) In order to perform the measurement task of measurement task pool plurality simultaneously, it is necessary to hold the information about all the measurement tasks under activation. The maintenance means of the measurement task will be called the task pool 320. What is necessary is just to make DS of the task pool 320 into the form where the task information 3210 was enumerated, as shown in drawing.6. The content of the task information 3210 contains demand [of a task ID 3211 and a task] former 3212, the definition information 310 on a measurement task, the progress situation 32130 of a task, and a time stump 32140.

[0038] A task ID 3211 is an identifier for identifying two or more measurement tasks uniquely, and should just set up the value which does not overlap the existing measurement task at the time of measurement task registration.

[0039] Requiring agency 3212 of a task is information which shows the registrant of a measurement task, and when outputting a measurement result to the registrant of a measurement task, in order that the measurement result output section 116 may know where [of two or more measurement control units 12] it should return, it is used. [0040] The measurement task definition information 310 is the definition information about the measurement task specified from the measurement control unit 12 mentioned above.

[0041] The progress situation 32130 of a task shows how far processing of a measurement task is progressing, and includes the end-of-task flag 32131, the progress 32132 of measurement, and the progress 32133 of an output. Such information is used when checking the progress situation of a measurement task.

[0042] A time stump 32140 is for recording the time about processing of a measurement task, and includes the date and time of creation 32141 of a task, and the measurement time 32142. Such information is used in order to know the freshness of a measurement task or a measurement result.

[0043] 2.2 The content 3110 of measurement included in the measurement means selection section measurement task definition information 310 makes the content of measurement specify, and does not make the class of measurement function 131 specify there according to the measurement item 3112 for [3111] measurement. This is for making assignment about measurement easier by what (it abstracting) is not made conscious [a measurement info broker's user] of the detail of a measurement function. [0044] However, since it is necessary to determine which measurement function 131 is used in case it measures actually, it is necessary to draw the class of measurement function from the content of assignment of the content 3110 of measurement. The information for performing the conversion is the measurement functional conversion table 330.

[0045] (1) The DS measurement functional conversion table 330 of the measurement functional conversion table 330 takes the form of enumeration of the response information 3310, as shown in <u>drawing 7</u>. Furthermore, the response information 3310 consists of the content 3110 of measurement, a measuring machine ID 3311, the measurement approach ID 3312, and a measurement item ID 3313.

[0046] The content 3110 of measurement is the same as what is contained in the measurement task definition information 310. A measuring machine ID 3311 is the formula alias name of the machine which has a measurement function corresponding to the content 3110 of measurement, for example, an IP address enters. The measurement approach ID 3312 is an identifier about the class of the measurement approach, for example, "SNMP/RMON", "CIM/WMI", etc. enter. The measurement item ID 3313 is the identifier of the content of measurement, for example, the object name of SNMP, the instance name of CIM, etc. enter.

[0047] By defining the measurement functional conversion table 330 beforehand, the suitable measurement approach and the measurement function 131 can be chosen now according to the content of the content 3110 of measurement into the measurement info broker 110.

[0048] (2) The example of the measurement functional conversion table 330 is shown in example drawing.8 of the measurement functional conversion table 330. The semantics of the party eye of data is as follows, and performs the same interpretation for other lines. In order to measure "the availability of C drive" of "server_1", "the FreeSpace attribute of the instance of Win32_LogicalDisk.DeviceID="C:"" is referred to by the measurement approach of "CIM/WMI" to "server_1."

approach of "CIM/WMI" to "server_l."

[0049] Thus, the content 310 of measurement can be specified with the expression for which it does not depend on the class of measuring machine 131 by performing conversion by the measurement functional conversion table 330 is not used, but you may make it specify the direct measuring machine ID 3312, the measurement approach ID 3312, and the measurement item ID 3313 within the measurement task definition information 310. When it does in this way, the time and effort which registers a measurement item into the measurement functional conversion table 330 can be omitted (however, in the case of registration of a measurement task, the information input of the level near mounting is needed, and registration of a measurement task becomes complicated).

[0051] (3) Although it is bases to process the one content of measurement by the measurement task of one two or more assignment, since the number of a measurement task increases when repeating the same measurement, the overhead which processing of a measurement task takes is worrisome. Therefore, you may make it process the measurement item for [by one one-time measurement task / two or more] measurement. [0052] For example, it is possible to perform the same content of measurement to two or more objects by writing together two or more objects, and to return two or more measurement results, or the total value and the average of measured value by assignment for [3111] measurement. Moreover, using metecharacters, such as an asterisk and question mark, is also considered instead of writing together two or more objects. For example, application of measuring to all the devices in the network which can measure the measurement item 3112 specified that it chooses only an asterisk can be considered.

[0053] Moreover, performing two or more measurement by writing together two or more measurement items in the measurement item 3112 is also considered.

[0054] In addition, what is necessary is for it to be possible that a measurement result also becomes plurality, if the measurement item for measurement becomes plurality, but just to perform returning two or more measurement results as they are in that case, or returning an average value or total value etc. (when for a measurement result to be numeric data).

[0055] 2.3 The measurement directions section measurement directions section 113 has the function to direct measurement to the measurement function 131, according to the measurement approach and measurement function which were chosen in the measurement means selection section 112. Specifically, measurement is directed by making the measurement item ID into the parameter for measurement using the means of the measurement approach ID 3312 to the measuring machine ID 3311 drawn in the measurement means selection section 112. For example, when processing the information on the party eye of <a href="mailto:drawning-recorded-section-party-re

"Win32_LogicalDeviceID="C:"" is published to "server_1" using the interface (API) of
"CIMWMI" (and let the "FreeSpace" attribute of the result to which it came on the
contrary be a measurement result).

[0056] What is necessary is just to take the form which prepares the measurement directions section 113 according to the class of the measurement approach to be used in the case of mounting of the measurement directions section 113. For example, the exclusive modularization of the measurement directions section for CIM, the measurement directions section for ping, the measurement directions section for SNMP, etc. is carried out. Moreover, mounting of the measurement directions section 113, and an addition/deletion of the measurement directions section 113 become easy by unifying the interface between the measurement means selection section 112 and the measurement directions section 113 (refer to Section 2.7 (3)).

[0057] (1) The function (the measurement approach specified by the measurement approach ID 3312 of the measurement functional conversion table 330) of the custom program measurement directions section 113 is not limited to what carries out mediation to the measurement section 131 (following and pons delivery type). It may be the custom program which analyzes by carrying out two or more measurement processings, in order to obtain a more advanced measurement result.

[0058] For example, when it is required to analyze synthetically the information acquired by SNMP and the information acquired by CIM, from the measurement control unit 12, those measurement tasks are defined according to an individual, and are performed, and processing in which the obtained result is analyzed is needed. When there are few measurement items, defining a measurement task according to an individual and performing it is also considered, but if a measurement item becomes a large number, the overhead (overheads, such as a communications traffic between the measurement control unit 12, the communications traffic between the measurement info brokers 110, measurement tasking on the measurement info broker 110 and the measurement info broker 110, and an output destination change 14) which activation of a measurement task takes will become large.

[0059] Then, if it is made to output only a required result to an output destination change 14 after offering a kind of macro function, performing two or more measurement

processings by performing one measurement task and analyzing those measurement results with a custom program, the overhead at the time of publishing said a majority of measurement tasks is mitigable.

[0060] What is necessary is just to enable the definition by the measurement functional conversion table 330 so that a custom program can be called from a measurement task like the function (measurement directions function of the type which carries out mediation to the measurement section 131 corresponding to SNMP, CIM, etc.) of the usual measurement directions section 113 (the class of SNMP, or CIM and a custom program is distinguished by the measurement approach ID 3312).

[0061] In addition, you may enable it to call said mediation type of other measurement directions section 113 and other custom programs (or for it to be the same) within a custom program.

[0062] 2.4 Work of the measurement result collection section measurement result collection section 114 is collection of a measurement result, and plastic surgery of a measurement result.

[0063] (1) Although collection drawing 3 of a measurement result has divided and described the measurement directions section 113 and the measurement result collection section 114, measurement directions and collection of a measurement result are one actually in many cases. For example, in activation of SNMP, or CIM and ping, the return value at the time of performing measurement directions (inquiry issuance) brings a measurement result. However, it is also considered for the reasons of measurement taking time amount that collection is performed to asynchronous as a result of measurement directions, and the measurement directions section 113 and the measurement result collection section 114 serve as another processing in that case.

[0064] The measurement result collection section 114 will usually be prepared like the measurement directions section 113 according to the class of the measurement approach (the object for SNMP, the object for CIM, for ping, etc.).

[0065] (2) It is good to process the information which did not make information (measurement result) sent from the plastic surgery measurement function 131 of a measurement result a measurement info broker's measurement result as it was, but was sent from the measurement function 131. Informational processing has deletion of excessive data, the addition of extra information, and unification of the format of a measurement result.

[0066] (2) -1 It must be removed when excessive data are contained in the measurement result sent from the deletion measurement function 131 of excessive data. For example, even if it performs ping in order to measure the network response time, the address, an explanatory note, etc. of the destination of ping are contained in the activation result of ping, and these are not related to the object of measurement.

[0067] (2) -2 The addition of extra information: The time stump when measuring to the measured information may be added. It becomes easy to identify the freshness of a measurement result by this.

[0068] (2) -3 Unification of the format of a measurement result: The information formats of the result sent from the measurement function 131 according to the class of measurement function 131 differ. For example, in SNMP and CIM, it differs and the same is said of ping. When the formats of the information passed to the measurement result output section 116 from the measurement result output section 114 differ for

every class of the measurement approach, it must stop therefore, having to prepare the measurement result output section for every class of the measurement approach. It is better to unify the information passed to the measurement result output section 116 from the measurement result collection section 114, in order to avoid this. Also in case the measurement result collection section 114 corresponding to the new measurement function 131 is added by doing so later, it becomes unnecessary moreover, to change the measurement result output section 116 (refer to Section 2.7 (3)).

[0069] 2.5 The measurement result output destination change selection section measurement result output destination change selection section 115 chooses the output destination change of the measurement result collected in the measurement result collection section 114 based on the content of the measurement result output method 3130 contained in the measurement task definition information 310. The following objects can be considered as an output destination change of a measurement result. [0070] (1) Return the registrant measurement result of a measurement task to the registrant of a measurement task. For example, when a measurement task is registered from the console of a certain measurement control unit 12, it returns to the console (it displays on a screen). When the registrant of a measurement task is application, it returns to the application similarly.

[0071] (2) Output a measurement result to the shared directory in a file / data-base-measurement info broker and on other machines. When measuring periodically, a log file is formed by recording by adding a postscript to one file. a database — a file — the same . [0072] (3) Output a measurement result to the application (distributed objects, such as CORBA and DCOM, are included) and the communication link ports (event transmission of a serial port output, an SNMP trap, etc.) which exist on the machine by which the output measurement info broker to application or a communication link port is working, or the other machine.

[0073] It supplements about proper use of these three methods. (1) is standard usage, and it is suitable to check a measurement result on a console screen. What is necessary is just to use (2), when transmission of a measurement result is asked for a sex instancy since it becomes the so-called Push type of transmission of transmitting information to an informational receiver by informational provider initiative. Moreover, what is necessary is just to use it, when many information users share the same measurement result since (3) becomes the so-called Pull type of information transfer of going information by informational reception hand initiative picking.

[0074] Even if it uses together two or more measurement result types of output to one or more measurement task with a natural thing, it is satisfactory at all.

[0075] 2.6 The measurement result output section measurement result output section 116 has the function which outputs the measurement result processed in the measurement result collection section 114 to the measurement result output destination change 14. What is necessary is just to prepare the processing facility corresponding to the types (a file, a database, application, communication link port, etc.) of the output destination change of the measurement result stated with Section 2.5.

[0076] In addition, the storage region only for measurement results is secured in a measurement info broker, and you may enable it to share a measurement result between making it accessible from other machines by two or more machines (information user) in the database. The example of the storage region (measurement result hangar) is shown in

drawing 9.

[0077] (1) The measurement result hangar measurement result hangar 30 is a list of measurement results 3410, and constitutes the measurement result 3410 from a task ID 3211, the interval measurement branch number 3411, measurement task definition information 310, a time stump 32140, and a measurement result 3412 further. [0078] The measurement result ID 3411 and the measurement result branch number 3412 are for identifying a measurement result uniquely, and in case they register a measurement result, they should just give the identifiers (or number etc.) which do not overlap the content specified by other measurement results 3410. The reason for having prepared two kinds of ID of a measurement result is because it assumed assigning the former to the sequence number at the time (it generating by periodic measurement etc.) of measuring multiple times for the latter by one measurement task to the measurement task ID 3211, respectively. By carrying out like this, the response relation between a measurement task and a measurement result can be expressed. Of course, the measurement result branch number 3412 is omitted, and it is satisfactory even if it makes it the form where a measurement result is identified by the measurement result ID 3411. [0079] The measurement task definition information 310 is the measurement conditions used in order to obtain the measurement result. Especially, this item may be omitted, when unnecessary.

[0080] The measurement time 32142 stores the time which measured as information for getting to know the freshness of a measurement result.

[0081] The measurement result 3413 is the storage area of a measurement result.

[0082] In addition, what is necessary is just to mount the measurement result hangar 340 on a file system or a database.

[0083] 2.7 At the measurement info broker Management Department measurement info broker Management Department 117, it has the function to perform various managements in the measurement info broker 110.

[0084] Management of the system of a measurement info broker including activation of a measurement task at large is performed. A management item is four, management of a measurement task, management of a measurement functional conversion table, management of various modules, and management of a measurement result hangar. [0085] What is necessary is to give a console to the measurement control unit 12 and just to enable it to direct the various contents of management on the console screen about a management activity to be managed according to a help. Drawing 10 showed the management menu screen 5010 of the measurement info broker Management Department 117 displayed on the console of the measurement control unit 12, and is equipped with the carbon button (5011-5014) and the termination carbon button 5015 corresponding to a management item of the measurement info broker Management Department 117 which mentioned above. In what each carbon button is pushed for (it chooses), it shifts to each management item (screen).

[0086] Hereafter, four management items (above-mentioned) which the measurement info broker Management Department 117 processes are explained.

[0087] (1) The management measurement task of a measurement task is registered into the task pool 320, and since it performs, management of a measurement task can be put in another way as management of the task pool 320. As a management item of the task pool 320, deletion of the measurement task (task information 3210) registered into new

registration of a measurement task and the task pool 320, Make Changes, etc. occur. [0088] New registration of a measurement task is realized in the form in which the task information on the task pool 320 carries out additional registration as Section 2.1 described it. Moreover, deletion of the measurement task in the task pool 320 is realized in the form where the specific task information registered into the task pool 320 is deleted. It corresponds in the form where the task information in the task pool 320 is changed, like [Make Changes / of a measurement task] them.

[0089] (1) -1 Measurement task management screen <u>drawing 11</u> is the measurement task management screen 5020. The list 5021 of measurement tasks shows the list of the task information which exists in a task pool, and the line by which inverse video is carried out shows that current selection of the task information is made.

[0090] The new carbon button 5022 is a carbon button pushed in case a measurement task is newly registered, and after it shifts to the measurement task setting screen A5030 and inputs information equivalent to the measurement task definition information 310 by pushing this carbon button, it registers that content of an input into a task pool. [0091] The task information chosen if the detailed information of the task information chosen if the detail carbon button 5023 is pushed is displayed and the deletion carbon button 5024 is pushed is deleted. If the closed carbon button 5025 is pushed, a measurement task management screen will be ended and it will return to the management menu screen 5010.

[0092] (1) -2 Measurement task setting screen A <u>drawing 12</u> is what showed the measurement task setting screen A5030, and it is used in order to input the setting-out item about the measurement approach of a measurement task.

[0093] The content set up in the measurement functional setting-out column 5032 is equivalent to the content 3110 of measurement within the measurement task definition information 310. Similarly, the content set up in the measurement approach setting-out column 5033 is equivalent to the measurement result collection approach 3120 within the measurement task definition information 310. In addition, it shifts to the measurement task setting screen B in what the output method tab 5041 is pushed for (it chooses). Moreover, the content of setting out is saved by pushing the O.K. carbon button 5034 (it registers into a task pool), and it shifts to the management screen (Maine) 5020 of a measurement task, and it shifts to the management screen (Maine) 5020 of a measurement task without saving the content of setting out by pushing Cancel button 5035.

[0094] (1) -3 Measurement task setting screen B <u>drawing 13</u> is what showed the measurement task setting screen B5040, and it is used in order to input the setting-out item about the output method of a measurement result.

[0095] The output destination change list 5042 is a list of the output destination changes set to the measurement tasks concerned. In this example, since it can have two or more output destination changes 31320 of measurement task definition information (refer to drawing.5), a setting-out screen can also respond to two or more output destination change assignment. The party of the output destination change list 5042 is equivalent to a part for even the output destination change 31320 of the measurement task definition information 310.

[0096] By pushing the additional carbon button 5043, it shifts to the measurement task setting screen C5050, and an output destination change is added. Moreover, by pushing

the detail carbon button 5044, it shifts to the measurement task setting screen C5050, and the content of setting out of the output destination change chosen within the output destination change list 5042 is changed. And the output destination change chosen within the output destination change list 5042 is deleted by pushing the deletion carbon button 5045.

[0097] In addition, it shifts to the measurement task setting screen B in what the measurement approach tab 5031 is pushed for (it chooses). Moreover, the content of setting out is saved by pushing the O.K. carbon button 5045 (it registers into a task pool), and it shifts to the management screen (Maine) 5020 of a measurement task, and it shifts to the management screen (Maine) 5020 of a measurement task without saving the content by pushing Cancel button 5046.

[0098] (1) -4 Measurement task setting screen C drawing 14 is what showed the measurement task setting screen C5050, and it is used in order to input the setting-out item about the output method of the measurement result of a measurement task. [0099] The content set up in the output destination change setting-out column 5051 is equivalent to the class 31321 of output destination change and ID31322 of an output destination change which are contained in the measurement task definition information 310. Moreover, the content set up in the content setting-out column 5052 of an output is equivalent to the output item 31323 included in the measurement task definition information 310. Similarly, the content set up in the coding setting-out column 5053 is equivalent to the coding method 31324 contained in the measurement task definition information 310.

[0100] In addition, the content of setting out is saved by pushing the O.K. carbon button 5054 (it registers into a task pool), and it shifts to the measurement task setting screen B5040, and it shifts to the measurement task setting screen B5040 without saving the content of setting out by pushing Cancel button 5055.

[0101] (2) The management items of the management measurement functional conversion table 330 of a measurement functional conversion table are an addition, modification, and deletion of the response information 3310 included in the measurement functional conversion table 330.

[0102] Drawing 15 shows the measurement functional conversion table management screen 5060. In the response information list 5051, the list of response information is displayed and a party is equivalent to a part for even the response information 3310. [0103] The response information 3310 is added by pushing the additional carbon button 5052. Moreover, setting out is changed about the response information 3310 chosen within the response information list 5051 by pushing the modification carbon button 5053. And the response information 310 chosen within the response information list 5051 is deleted by pushing the deletion carbon button 5054. The management screen (Maine) 5060 of a measurement functional conversion table is ended by pushing the closed carbon button 5055, and it returns to the management menu screen 5010. [0104] (3) management of various modules — in order to correspond to various measurement technique and output forms, it is good to carry out the modularization of the measurement directions section 113, the measurement result collection section 114, and the measurement result output section 116.

[0105] The measurement info broker 110 is the module definition table 350 which records the information about an available module, and <u>drawing 16</u> serves as a list of

module definitions 3510. The module definition 3510 consists of the stereo 3513 of an identifier 3511, the functional type 3512, and a module further.

[0106] There is an identifier 3511 in order to connect the measurement approach ID 3312 in the measurement functional conversion table 330 or the content which has the class 31321 and response relation of an output destination change within the measurement task definition information 310, and was specified by the measurement approach ID 3312 or the class 31321 of output destination change, and a module (stereo). The functional type 3512 is information which shows the class (exception of measurement, collection, and an output) of modular function. The modular stereos 3513 are the information (a storing place, an object name, etc. of a program code) indicating a modular stereo.

[0107] <u>Drawing 17</u> is a module management screen. The module list 5071 shows the list of the module registered on the measurement info broker 110, and the party has become the definition for a module piece.

[0108] A module is added by pushing the additional carbon button 5072. Moreover, setting out about the module chosen within the module list 50710 is changed by pushing the modification carbon button 5073. And the module chosen within the module list 50710 is deleted by pushing the deletion carbon button 5074. The management screen (Maine) 5070 of a measurement functional conversion table is ended by pushing the closed carbon button 5075, and it returns to the management menu screen 5010. [0109] (4) The management item of the management measurement result hangar 340 of a measurement result hangar is the content display and deletion of the measurement result 3410 which are registered into this hangar.

[0110] Drawing 18 shows the measurement result hangar management screen 5080. The measurement result list 5081 displays the list of the measurement results registered into the measurement result hangar 340, and a party is equivalent to one measurement. [0111] By pushing the detail carbon button 5082, the content of the measurement result 3410 chosen within the measurement result list 5081 is displayed. Moreover, the measurement result 3410 chosen within the measurement result list 5081 is deleted by pushing the deletion carbon button 5083. And the management screen (Maine) 5080 of a measurement result hangar is ended by pushing the closed carbon button 5084, and it returns to the management menu screen 5010.

[0112]

[Effect of the Invention] As mentioned above, according to this invention, the management application which needs measurement information can receive measurement information with a single access means, without using the access means depending on a measurement function. By this, development of the management application using measurement information and mounting to a system become easy.

[0113] Moreover, it becomes easy to share a measurement result between holding a measurement result in a measurement info broker, or outputting a measurement result to objects other than those who demanded measurement information (transmission) among two or more measurement information users (management application).

DESCRIPTION OF DRAWINGS

[Brief Description of the Drawings]

[Drawing 1] It is the block diagram showing the structure of a system concerning the

operation gestalt of this invention.

<u>Drawing 2</u>] It is the block diagram showing the hardware configuration of the measurement control unit concerning the operation gestalt of this invention, a measurement info broker, a measurement result output destination change, a measurement function, and the hardware configuration for measurement.

[Drawing 3] It is a block diagram centering on the internal configuration of the measurement info broker concerning the operation gestalt of this invention.

[Drawing 4] It is processing flow drawing of the measurement info broker concerning the operation gestalt of this invention.

[Drawing 5] It is drawing showing the content of the measurement task definition information processed by the measurement info broker concerning the operation gestalt of this invention.

[Drawing 6] It is drawing showing the content of the task pool which the measurement info broker concerning the operation gestalt of this invention holds.

[<u>Drawing 7</u>] It is drawing showing the content of the measurement functional conversion table which the measurement info broker concerning the operation gestalt of this invention holds.

[<u>Drawing 8</u>] It is drawing showing the example of a content of the measurement functional conversion table which the measurement info broker concerning the operation gestalt of this invention holds.

gestant of this invention noise.

[Drawing 9] It is drawing showing the content of the measurement result hangar which the measurement info broker concerning the operation gestalt of this invention holds.

[Drawing 10] It is drawing showing the example of a display of the management menu screen displayed on the measurement control unit concerning the operation gestalt of this invention.

[<u>Drawing 11</u>] It is drawing showing the example of a display of the measurement task management screen displayed on the measurement control unit concerning the operation gestalt of this invention.

[<u>Drawing 12</u>] It is drawing showing the example of a display of the measurement task setting screen A displayed on the measurement control unit concerning the operation gestalt of this invention.

[Drawing 13] It is drawing showing the example of a display of the measurement task setting screen B displayed on the measurement control unit concerning the operation cestalt of this invention.

[Drawing 14] It is drawing showing the example of a display of the measurement task setting screen C displayed on the measurement control unit concerning the operation gestalt of this invention.

[Drawing 15] It is drawing showing the example of a display of the measurement functional conversion table management screen displayed on the measurement control unit concerning the operation gestalt of this invention.

[Drawing 16] It is drawing showing the content of the module definition table which the measurement info broker concerning the operation gestalt of this invention holds.

[Drawing 17] It is drawing showing the example of a display of the module management screen displayed on the measurement control unit concerning the operation gestalt of this invention.

[Drawing 18] It is drawing showing the example of a display of the measurement result

hangar management screen displayed on the measurement control unit concerning the operation gestalt of this invention.

[Description of Notations]

110 [— The measurement directions section, 114 /— The measurement result collection section, 115 /— The measurement result output destination change selection section, 116 /— The measurement result output section, 12 /— A measurement control unit, 131 /— A measurement function, 132 /— 14 for measurement /— Measurement result output destination change.]— A measurement info broker, 111 — The measurement task management section, 112 — The measurement mass selection section, 113

CLAIMS

[Claim(s)]

[Claim 1] In the computer system which consists of a computer machine, a network device, etc. The measurement function to have the function to measure or check the condition of resources, such as hardware, such as said computer machine, network device, etc., and firmware, software, and to transmit to others said result measured or checked. The measurement to said measurement function from the information which specifies a measurement item, or the class of directions means of a check. Or the class of collection means of the measurement from said measurement function or a check result is drawn. The computer system characterized by having the measurement info broker who performs collection of the measurement which the measurement to said measurement function, directions of a check, or said measurement function offers, or a check result. [Claim 2] In the computer system which consists of a computer machine, a network device, etc. The measurement function to have the function to measure or check the condition of resources, such as hardware, such as said computer machine, network device, etc., and firmware, software, and to transmit to others said result measured or checked, the information which specifies the object for measurement, and the information which specifies a measurement item -- since - with the information which specifies said measurement function The class of measurement directions means against said measurement function, or the class of measurement result collection means from said measurement function, the computer system which carries out guidance appearance and is characterized by having the measurement info broker who performs collection of the measurement which the measurement to said measurement function, directions of a check, or said measurement function offers, or a check result. [Claim 3] It is the computer system carry out having a means to hold more than one in information required in case the measurement for which issuance processing or said measurement function of directions of measurement of as opposed to [are a computer

information required in case the measurement for which issuance processing or said measurement function of directions of measurement of as opposed to [are a computer system according to claim 1 or 2, and] said measurement function under current implementation of an operation schedule in said measurement info broker or a check provides, or collection processing of a check result is performed as the description. [Claim 4] It is the computer system characterized by it being a computer system according to claim 1 or 2, and said measurement info broker being able to output the measurement or the check result collected from said measurement function to two or more measurement result output destination changes.

[Translation done.]